

FOR PLANNING PURPOSES

SERVICE BULLETIN

SERVICE BULLETIN NO: 30-003

REF NO: 012

MODIFICATION NO:

ATA CHAPTER: 30

REPLACE THE AOA PLATE (TEMPERATURE) CONTROLLER (P/N: 975.44.21.417) {BFG 3E2459-3}

1. Planning Information

A. Effectivity

- (1) All aircraft from MSN 101 up to and including MSN 153, which are equipped with the AOA plate (temperature) controller (P/N: 975.44.21.417) {BFG 3E2459-3}.
- (2) This Service Bulletin will be incorporated prior to delivery on aircraft MSN 154 and subsequent.

B. Reason

To eliminate the possibility of output malfunction at high temperatures, this Service Bulletin introduces a modified controller which has an improved high temperature reliability.

C. Description

Accomplishment of this Service Bulletin consists of completing the following tasks:

- (1) Locate the AOA plate (temperature) controllers inside the LH and RH wings.
- (2) Check the serial number of each controller fitted.

If the numerical Serial Number of a controller is U0215 or lower and is not annotated with "SB30-1", it must be replaced with a new component which will have a numerical Serial Number higher than U0215 or will be annotated with "SB30-1".

- (3) If an AOA plate (temperature) controller is replaced, test the system.
- (4) Record compliance with the Service Bulletin in the Aircraft Logbook.

D. Compliance

Mandatory.

This task must be done before 31 December 1996 or concurrent with the incorporation of SB 30-001 (Modification to the Anti-icing and De-icing Systems), whichever is later.

PILATUS
PC XII
SERVICE BULLETIN

FOR PLANNING PURPOSES

E. Approval

The technical aspects of this Service Bulletin have been approved by the Federal Office for Civil Aviation (FOCA) of Switzerland.

NOTE: PILATUS advises Operators/Owners to check with their local Airworthiness Authorities for any changes, local regulations or sanctions that may affect the embodiment of this Service Bulletin.

F. Manpower

Task	Man-hours
Preparation	0.5
Replacement *	0.75
Test *	0.5
Close-Up	0.25
TOTAL MAN-HOURS	2.0

NOTE: Man-hours figures are calculated for the unit installed in the aircraft and represent the total time estimated for the task.

NOTE: * = If change is required.

G. Material - Cost and Availability

(1) Material

Operators should send orders for Service Bulletin modification kits, to:

PILATUS AIRCRAFT LTD,
CUSTOMER LIAISON MANAGER,
CH 6370 STANS,
SWITZERLAND.

Tel No: +41 41-6196 233
Fax No: +41 41-6103 351

or

Contact your Authorized PILATUS PC-12 Service Center.

NOTE: Operators are requested to advise Pilatus Aircraft Ltd. of the Manufacturers Serial Number (MSN) and the flying hours of aircraft which are allocated for this Service Bulletin.

(2) Cost and Availability