

Service Bulletin No: 25-045

Ref No: 378

Modification No: EC-17-0173

ATA Chapter: 25

EQUIPMENT AND FURNISHINGS - FLIGHT COMPARTMENT - INTRODUCTION OF HEADSET HOLDERS ON THE COCKPIT SIDEWALLS**1. Planning Information****A. Effectivity**

PC-12, PC-12/45, PC-12/47 Series aircraft MSN 101 thru 888, except MSN 545.

PC-12/47E aircraft MSN 545, 1001 and up without headset holders installed on the cockpit sidewalls.

B. Concurrent Requirements

None.

C. Reason**(1) Problem**

There are currently no headset holders on the cockpit sidewalls.

(2) Solution

Install headset holders on the cockpit sidewalls.

D. Description

This Service Bulletin gives the data and instructions to install headset holders on the cockpit sidewalls.

E. Compliance

Optional.

F. Approval

The technical content of this Service Bulletin is approved under the authority of DOA No. EASA. 21J. 357.

PILATUS advises Operators/Owners to check with their designated Airworthiness Authority for any changes, local regulations or sanctions that may affect the embodiment of this Service Bulletin.

G. Copyright and Legal Statement

© Pilatus Aircraft Ltd. This document contains proprietary information that is protected by copyright. All rights are reserved. No part of this document may be copied, reproduced or translated to other languages without the prior written consent of Pilatus Aircraft Ltd.

In connection with the use of this document, Pilatus does not provide any express or implied warranties and expressly disclaims any warranty of merchantability or fitness for a particular purpose. This document contains trade secrets, confidential and/or proprietary information of Pilatus and technical data subject to export control laws and regulations, including the U.S. Export Administration Regulations (EAR). Disclosure or distribution of this document contrary to the EAR, and other laws and regulations, is strictly forbidden. The above restrictions may apply to data on all pages of this document.

H. Manpower

Description	Manhours
Preparation	1.5
Modification	5.0
Close up	1.5
TOTAL MAN-HOURS	8.0

NOTE: Man-hours do not include the drying time for paints or the cure time for adhesives.

I. Weight and Balance

Not changed.

J. Electrical Load Change Data

Not changed.

K. Software

Not changed.

L. References

NOTE: AMM references are given without the model prefix. For PC-12, PC-12/45, PC-12/47 Series aircraft use the prefix 12-A, for PC-12/47E Series aircraft use the prefix 12-B.

Aircraft Maintenance Manual (AMM)

20-31-00-00A-070A-A	20-50-00-00A-901A-A
24-00-00-00A-901A-A	25-10-03-00A-920A-A

M. Publications Affected

Illustrated Parts Data (IPD).

N. Interchangeability of Parts

Not applicable.

2. Material Information**A. Material - Price and Availability**

Operators that require additional information and/or Service Bulletin Material should contact their authorized Pilatus Service Center, or Pilatus Customer Support on www.pilatus-aircraft.com → contact us

NOTE: Part Numbers given in this Service Bulletin are correct at the time of approval. Pilatus Aircraft Ltd. reserves the right to change the part numbers as necessary. Part numbers of items delivered with the kit are correct when the kit is dispatched. This could lead to differences between those part numbers quoted in this Service Bulletin and the kit if parts are superseded. Operators are requested to check the IPD for delivered parts which differ from those listed in the Service Bulletin Materials Kit List.