

FOR PLANNING PURPOSES

SERVICE BULLETIN

SERVICE BULLETIN NO: 04-004

REF NO: 042

MODIFICATION NO: 97-0323

ATA CHAPTER: 04

ARGENTINEAN REGISTRATION OF THE PC-12, PC-12/45 AND PC-12/47 AIRCRAFT

1. Planning Information

A. Effectivity:

All PC-12, PC-12/45 and PC-12/47 aircraft which require Argentinean Certification, up to and including MSN 999, except for aircraft MSN 545.

B. Concurrent Requirements

None.

C. Reason

To have the aircraft in compliance with Argentinean Airworthiness requirements.

D. Description

This Service Bulletin gives the data and instructions necessary to:

- (1) Install the First Aid Kit (Ref. Fig. 1).
- (2) Install a placard on the fire extinguisher (Ref. Fig. 2).
- (3) Install the 406 MHz Emergency Locator Transmitter (ELT) in accordance to the Vendor recommendations.
- (4) Install all required external markings, as given Engineering Drawing No: 511.21.12.005, in the Spanish language.
- (5) Install all required internal placards, as given Engineering Drawing No: 511.34.12.018 (for the Corporate Utility variant) or Engineering Drawing No: 511.21.12.019 (for the Executive variant).

NOTE: The new placards may be bilingual in English and Spanish.

- (6) Make sure that the PC-12 SB 28-002 is incorporated.
- (7) Amend the Airplane Flight Manual to Argentinean Configuration.

SERVICE BULLETIN

Revision 1 changes the Effectivity and updates the Service Bulletin to the latest standard.

NOTE: Only the Service Bulletin is updated. The drawings and/or documents listed in the Appendix(es) are not included. Operators who wish to accomplish this Service Bulletin should apply to Pilatus Aircraft Ltd. for the latest revisions of the drawings and/or documents listed in the Appendix(es).

E. Compliance

Mandatory for all aircraft to be registered in Argentina.

NOTE: Depending on the specific operation of the aircraft (e.g. Air Taxi), additional items may be required by the Argentinean Airworthiness Authorities. The Operator is responsible to make sure that all additional operation requirements are complied with.

F. Approval

The technical content of this Service Bulletin is approved under the authority of DOA No. EASA. 21J. 357.

PILATUS advises Operators/Owners to check with their local Airworthiness Authorities for any changes, local regulations or sanctions that may affect the embodiment of this Service Bulletin.

G. Manpower

	Total
Preparation	1.0
Modification	8.0 + Paint drying time
Close up	0.5
TOTAL MAN-HOURS	9.5

NOTE: Man-hours figures are calculated for units installed in the aircraft and represent the total time estimated for the task.

H. Weight and Balance

(1) Weight Change

Not affected.

(2) Moment Change

Not affected.

I. Electrical Load Data

Not applicable.

J. Software

Not changed.

K. References

None.

L. Publications Affected

Illustrated Parts Catalog (IPC), Chapter 11-00-00 - Placards.

Airplane Flight Manual (Report No: 01973-001).

M. Interchangeability of Parts

Not applicable.

2. Material Information

A. Material - Price and Availability

Operators should send orders for Service Bulletin Modification Kits, to their Authorized Pilatus Service Center or:

PILATUS AIRCRAFT LTD.,
CUSTOMER SUPPORT MANAGER,
CH-6371 STANS,
SWITZERLAND

General Aviation:
Tel: + 41 41 619 6208
Fax: + 41 41 619 7311
eMail: SupportPC12@pilatus-aircraft.com

PILATUS BUSINESS AIRCRAFT LTD.,
PRODUCT SUPPORT DEPARTMENT
11755 AIRPORT WAY
BROOMFIELD, CO 80021.
UNITED STATES OF AMERICA

Tel: 303 465 9099
Fax: 303 465 6040
eMail: Productsupport@PilBal.com

PILATUS AUSTRALIA (PTY.) LTD,
17 JAMES SCHOFIELD DRIVE,
ADELAIDE AIRPORT SA 5950,
AUSTRALIA

Tel: (08) 8234 4433
Fax: (08) 8234 4499
Free Call: 1800 445 007
eMail: info@pilatus.com.au

Operators are requested to advise Pilatus Aircraft Ltd, of the Manufacturer's Serial Number (MSN) and the flying hours of aircraft which are affected by this Service Bulletin.