

FOR PLANNING PURPOSES

SERVICE BULLETIN

SERVICE BULLETIN NO: PC-12 24-001

REF NO: 013

MODIFICATION NO: 950984

ATA CHAPTER: 24

REPLACEMENT OF SECOND GENERATOR DRIVE HOUSING

1. Planning Information

A. Effectivity

- (1) All aircraft up to and including MSN 126.
- (2) This Service Bulletin will be incorporated prior to delivery on aircraft MSN 127 and subsequent.

B. Reason

To reduce the effect of possible vibration of the second generator mounting.

C. Description

Accomplishment of this Service Bulletin consists of completing the following tasks:

- (1) Remove the second generator.
- (2) Remove the old drive assembly.
- (3) Install the new drive assembly.
- (4) Install the second generator.

D. Compliance

Highly recommended.

E. Approval

The technical aspects of this Service Bulletin have been approved by the Federal Office for Civil Aviation (FOCA) of Switzerland.

NOTE: PILATUS advises Operators/Owners to check with their local Airworthiness Authorities for any changes, local regulations or sanctions that may affect the embodiment of this Service Bulletin.

PILATUS
PC12
SERVICE BULLETIN

FOR PLANNING PURPOSES

F. Manpower

Task	Man-hours
Preparation	1.00
Removal of old drive assembly	1.00
Installation of new drive assembly	1.00
Install the generator	0.50
Close-Up	0.50
TOTAL MAN-HOURS	4.00

NOTE: Man-hours figures are calculated for units installed in the aircraft and represent the total time estimated for the task.

G. Material - Cost and Availability

(1) Material

Operators should contact your Authorized PILATUS PC-12 Service Center or send an order, for this Service Bulletin modification kit, to:

PILATUS AIRCRAFT LTD,
CUSTOMER LIAISON MANAGER
CH 6370 STANS,
SWITZERLAND.

Tel No: +41 41-6196 233
Fax No: +41 41-6103 351

NOTE: Operators are requested to advise Pilatus Aircraft Ltd. of the Manufacturers Serial Number (MSN) and the flying hours of the aircraft which are allocated for this Service Bulletin.

(2) Cost and Availability

H. Tooling

None.

I. Weight and Balance

Not Affected.

J. References

Maintenance Manual, 24-30-02 and 24-30-04.
IPC, Chapter 24-30-00.

K. Publications Affected

AMM, 24-30-04, Page Block 401.
IPC, 24-30-00, Figure 03.