

**FOR PLANNING PURPOSES**

# SERVICE BULLETIN

SERVICE BULLETIN NO: 25-004

REF NO: 041

MODIFICATION NO:

ATA CHAPTER: 25

## EXECUTIVE TOILET WIRING MODIFICATION

### 1. Planning Information

#### A. Effectivity

- (1) All aircraft up to and including MSN 160, with the executive interior fitted.
- (2) This Service Bulletin will be incorporated prior to delivery on aircraft MSN 161 and subsequent.

#### B. Reason

It has been found that, in some cases, the fuse (F668 for the flush motor) in the executive toilet is wired incorrectly. The function of the toilet is not affected.

This Service Bulletin recommends that the wiring is examined and, if necessary, the wiring to be corrected to correspond to the wiring diagram (Ref. Fig. 1).

#### C. Description

Accomplishment of this Service Bulletin consists of completing the following tasks:

- (1) Get access to the toilet wiring.
- (2) Examine the wiring.
- (3) If necessary, correct the wiring.

#### D. Compliance

Recommended.

#### E. Approval

The technical aspects of this Service Bulletin have been approved by the Federal Office for Civil Aviation (FOCA) of Switzerland.

**NOTE:** PILATUS advises Operators/Owners to check with their local Airworthiness Authorities for any changes, local regulations or sanctions that may affect the embodiment of this Service Bulletin.

**≡PILATUS≡**  
**PC12**  
**SERVICE BULLETIN**

**FOR PLANNING PURPOSES**

**F. Manpower**

<b>Task</b>	<b>Man-hours</b>
Preparation	0,5
Inspection	0,5
Repair	0,5
Close-up	0,5
<b>TOTAL MAN-HOURS</b>	<b>2,0</b>

**NOTE:** Man-hours figures are calculated for units installed in the aircraft and represent the total time estimated for the task.

**G. Material - Cost and Availability**

**(1) Material**

Operators should contact their authorized PILATUS SERVICE CENTER, or contact the following for further information:

PILATUS AIRCRAFT LTD.  
CUSTOMER LIAISON MANAGER,  
CH-6371 STANS,  
SWITZERLAND.

Tel: + 41 41 619 6509  
Fax: + 41 41 610 3351

**NOTE:** Operators are requested to advise Pilatus Aircraft Ltd. of the Manufacturer's Serial Number (MSN), and the flying hours of the aircraft which are allocated for this Service Bulletin using the Service Bulletin Evaluation Form.

**H. Tooling**

None.

**I. Weight and Balance**

Not Affected.

**J. References**

Aircraft Maintenance Manual (AMM), Chapters 25-21-00.

**K. Publications Affected**

None.