

FOR PLANNING PURPOSES

PC-12

SERVICE BULLETIN

PILATUS AIRCRAFT LTD, STANS, SWITZERLAND

Service Bulletin No: 53-008 Ref No: 348

Modification No: EC-15-0510 **ATA Chapter:** 53

FUSELAGE - CENTER FUSELAGE INSTALL CHAFE PROTECTION TAPE ON THE FUSELAGE SKIN

1. **Planning Information**

A. **Effectivity**

All PC-12, PC-12/45, PC-12/47 and PC-12/47E aircraft MSN 101 and up.

B. **Concurrent Requirements**

None.

C. Reason

(1) **Problem**

Chafe damage of the fuselage skin has been reported.

(2) Cause

Chafing between fairing panels and the fuselage skin.

(3) Solution

Install chafe protection tape on the fuselage skin.

D. **Description**

This Service Bulletin gives the instructions and data necessary to install chafe protection tape on the fuselage skin.

Revision 1 to this Service Bulletin updates the length of anti-chafe tape for Part 1, 2 and 3. No rework is required for Operators who have already embodied this Service Bulletin at initial issue.

E. Compliance

Optional.

F. **Approval**

The technical content of this Service Bulletin is approved under the authority of DOA No. EASA.21J.357.

PILATUS advises Operators/Owners to check with their designated Airworthiness Authority for any changes, local regulations or sanctions that may affect the embodiment of this Service Bulletin.

Service Bulletin No: 53-008 Drat 1 Date: Feb 25/16 Rev No. 1 Date: May 18/16 Page 1 of 12



SERVICE BULLETIN

PC-12

G. Copyright and Legal Statement

© Pilatus Aircraft Ltd. This document contains proprietary information that is protected by copyright. All rights are reserved. No part of this document may be copied, reproduced or translated to other languages without the prior written consent of Pilatus Aircraft Ltd.

In connection with the use of this document, Pilatus does not provide any express or implied warranties and expressly disclaims any warranty of merchantability or fitness for a particular purpose. This document contains trade secrets, confidential and/or proprietary information of Pilatus and technical data subject to export control laws and regulations, including the U.S. Export Administration Regulations (EAR). Disclosure or distribution of this document contrary to the EAR, and other laws and regulations, is strictly forbidden. The above restrictions may apply to data on all pages of this document.

H. Manpower

The man-hours given are for the incorporation of this Service Bulletin during the Annual Inspection.

Task	MAN-HOURS		
	Part 1	Part 2	Part 3
Preparation	0.5	0.5	0.5
Modification	1.0	2.0	6.0
Close-Up	0.5	0.5	0.5
TOTAL MAN-HOURS	2.0	3.0	7.0

NOTE: Man-hours do not include drying time for paints.

A. Weight and Balance

Not changed.

B. Electrical Load Data

Not changed.

C. Software

Not changed.

D. References

NOTE: Throughout this Service Bulletin AMM/SRM references are given without the model

prefix.

For PC-12, PC-12/45 and PC-12/47 aircraft, prefix references with 12-A.

For PC-12/47E aircraft, prefix references with 12-B.

06-20-00-00A-040A-A	20-31-00-00A-070A-A	20-40-10-00A-901A-A
20-50-00-00A-901A-A	24-00-00-00A-901A-A	33-40-00-00A-903A-A
33-40-00-00A-903B-A	33-46-01-00A-920A-A	53-20-01-00A-664B-A

 Service Bulletin No:
 53-008
 Date: Feb 25/16

 Rev No.
 1
 Date:
 May 18/16
 Page
 2 of 12



FOR PLANNING PURPOSES

SERVICE BULLETIN PC-12

E. **Publications Affected**

AMM, IPC.

F. **Interchangeability of Parts**

Not interchangeable.

Service Bulletin No: 53-008 Date: Feb 25/16 Rev No. 1 Date: May 18/16 Page 3 of 12



SERVICE BULLETIN

PC-12

1. Material Information

A. Material - Price and Availability

Operators that require additional information and/or Service Bulletin materiel, should contact their Authorized Pilatus Service Center, or to:

PILATUS AIRCRAFT LTD CUSTOMER SUPPORT MANAGER CH-6371 STANS

SWITZERLAND

General Aviation:

Tel: + 41 41 619 3333 Fax: + 41 41 619 7311

eMail: SupportPC12@pilatus-aircraft.com

PILATUS BUSINESS AIRCRAFT LTD PRODUCT SUPPORT DEPARTMENT 11755 AIRPORT WAY BROOMFIELD, CO 80021 Tel: +1 303 465 9099 Fax: +1 303 465 6040

Tel: +61 8 8238 1600

eMail: SupportPC12@PilBal.com

PILATUS AUSTRALIA PTY LTD 17 JAMES SCHOFIELD DRIVE ADELAIDE AIRPORT SA 5950

UNITED STATES OF AMERICA

ADELAIDE AIRPORT S AUSTRALIA Fax: +61 8 8234 4499 Free Call: +61 1800 PILATUS (745 2887) eMail: SupportPC12@pilatus.com.au

Operators are requested to advise Pilatus Aircraft Ltd, of the Manufacturer's Serial Number (MSN) and the flying hours of aircraft which are affected by this Service Bulletin.

B. Material Necessary for Each Aircraft

NOTE:

Part Numbers given in this Service Bulletin are correct at the time of approval. Pilatus Aircraft Ltd. reserves the right to change the part numbers as necessary. Part numbers of items delivered with the Modification Kit are correct when the kit is dispatched. This could lead to differences between those part numbers quoted in this Service Bulletin and the Modification Kit if parts are superseded. Operators are requested to check the IPC for delivered parts which differ from those listed in the Service Bulletin Materials Kit List.

Service Bulletin No: 53-008 Date: Feb 25/16
Rev No. 1 Date: May 18/16 Page 4 of 12