



PILATUS AIRCRAFT LTD. CH-6371 STANS, SWITZERLAND

FOR PLANNING PURPOSES

SERVICE BULLETIN

SERVICE BULLETIN NO: 71-002

REF NO: 50

MODIFICATION NO: 970579

ATA CHAPTER: 71

MODIFICATION OF THE ENGINE FIRE WIRE

1. Planning Information

A. Effectivity

- (1) All aircraft up to and including MSN 200.
- (2) This Service Bulletin will be incorporated prior to delivery on aircraft MSN 201 and subsequent.

B. Reason

The clamps that locate the fire wire around the exhaust stub flanges, can induce chafe marks onto the fire detecting wire, this can cause a failure of the fire warning system.

This Service Bulletin introduces a new fire wire clamp around the exhaust stub flanges.

C. Description

Accomplishment of this Service Bulletin consists of the tasks that follow:

- (1) Remove the engine cowlings.
- (2) Do the modification.
- (3) Install the engine cowlings.

D. Compliance

Recommended.

E. Approval

The technical aspects of this Service Bulletin have been approved by the Federal Office for Civil Aviation (FOCA) of Switzerland .

NOTE: PILATUS advises Operators/Owners to check with their local Airworthiness Authorities for any changes, local regulations or sanctions that may affect the embodiment of this Service Bulletin.

F. Manpower Man-hours

Preparation	0,2
Modification	0,5
Close-Up	0,3
TOTAL MAN-HOURS	1,0

G. Material - Cost and Availability

(1) Material

Operators should send orders, for Service Bulletin modification kits, to their Authorized Pilatus PC-12 Service Center.

or:

PILATUS AIRCRAFT LTD,
CUSTOMER LIAISON MANAGER,
CH 6371 STANS
SWITZERLAND

Tel No: +41 416196 233
Fax No: +41 41-6103 351

NOTE: Operators are requested to advise Pilatus Aircraft Ltd. of the Manufacturer's Serial Number (MSN) and the flying hours of aircraft which are allocated for this Service Bulletin.

(2) Cost and Availability

H. Tooling

None.

I. Weight and Balance

Not Affected.

J. References

Aircraft Maintenance Manual (AMM), Chapters 71-00-02, 71-10-00, 78-10-01.

Illustrated Parts Catalog (IPC), Chapter 26-10-00.

K. Publications Affected

Aircraft Maintenance Manual (AMM), Chapters 71-00-02, 78-10-01.

Illustrated Parts Catalog (IPC), Chapter 26-10-00.