

SERVICE LETTER

SUBJECT: REPLACEMENT OF SEALANT PR1431, TYPES 1 AND 2

To all Customers and Operators:

Date: Feb 26/04

This Service Letter is issued to draw attention to the following information:

Replacement of Sealant PR1431, Types 1 and 2

PILATUS has been advised that sealant PR1431 Type I and PR1431 Type II are no longer available.

This Service Letter is to inform Operators that PILATUS recommends the following sealants as alternatives:

OLD SEALANT		ALTERNATIVE SEALANT	
Name	Part Number	Name	Part Number
PR1431 Type I	907.10.11.241	PS 892 C12	907.10.11.244
PR1431 Type II	907.10.11.242	PS 892 C24	907.10.11.243

Operators requiring further information on this subject, please contact one of the addresses given below:

PILATUS AIRCRAFT LTD.,
CUSTOMER SUPPORT MANAGER,
CH-6371 STANS,
SWITZERLAND.

General Aviation
Tel : + 41 41 619 6208
Fax: + 41 41 619 7311
eMail: SupportPC12@pilatus-aircraft.com
Government
Tel: + 41 41 619 6509
Fax: + 41 41 619 6224
eMail: rpaterson@pilatus-aircraft.com

PILATUS BUSINESS AIRCRAFT LTD.,
PRODUCT SUPPORT DEPARTMENT,
11755 AIRPORT WAY,
BROOMFIELD, CO 80021,
USA

Tel : 303 465 9099
Fax: 303 465 6040
eMail: Productsupport@PilBat.com

PILATUS AUSTRALIA (Pty.) LTD.,
PO BOX 732,
MARLESTON SA 5033,
AUSTRALIA

Tel : (08) 8234 4433
Fax: (08) 8234 4499
Free Call: 1800 445 007
eMail: info@pilatus.com.au

≡PILATUS≡
PC12
SERVICE LETTER

INTENTIONALLY BLANK