



PILATUS AIRCRAFT LTD. CH-6371 STANS, SWITZERLAND

SERVICE LETTER

SUBJECT: PRATT & WHITNEY (CANADA) ALERT SERVICE BULLETIN

To all Customers, Operators and Service Centers:

Date: Sep 27/07

This Service Letter is issued to draw attention to the following vendor information:

PRATT & WHITNEY (CANADA) ALERT SERVICE BULLETIN PT6A-72-A14410 - TURBOPROP ENGINE - INSPECTION OF THE SPARK IGNITERS.

Pratt & Whitney (Canada) have issued Alert Service Bulletin PT6A-72-A14410 which affects the engines installed on the PC-12 aircraft. The Service Bulletin recommends the inspection of the spark igniters to check the serial number of the igniters and, if necessary, replace the suspect igniter(s) with a serviceable item(s). The recommended compliance time is 50 flight hours. In addition, Pilatus recommends that all igniters held in store are checked.

Pilatus recommends that Customers, Operators and Service Centers do the Pratt & Whitney (Canada) Alert Service Bulletin PT6A-72-A14410 to make sure the igniter tip does not break off and enter the gas path. This can damage the engine.

Pilatus would also remind Customers, Operators and Service Centers of the dangers when work on the ignition system is performed. Make sure you obey the warnings which are in the Aircraft Maintenance Manual (AMM) when you work on the ignition system.

Operators requiring further information on this subject, please contact one of the addresses given below:

PILATUS AIRCRAFT LTD.,
CUSTOMER SUPPORT MANAGER,
CH-6371 STANS,
SWITZERLAND.

General Aviation
Tel : + 41 41 619 6208
Fax: + 41 41 619 7311
eMail: SupportPC12@pilatus-aircraft.com

PILATUS BUSINESS AIRCRAFT LTD.,
PRODUCT SUPPORT DEPARTMENT,
11755 AIRPORT WAY,
BROOMFIELD, CO 80021.
USA

Tel : 303 465 9099
Fax: 303 465 6040
eMail: Productsupport@PilBal.com

PILATUS AUSTRALIA (Pty.) LTD.,
17 James Schofield Drive,
Adelaide Airport SA 5950,
AUSTRALIA

Tel : +61 (08) 8234 4433
Fax: +61 (08) 8234 4499
Free Call: 1800 445 007
eMail: info@pilatus.com.au