

**AUTO FLIGHT - AUTOPILOT
TEMPORARY PLACARD INSTALLATION - PC-6/B2-H4 AIRCRAFT REGISTERED IN THE PEOPLE'S
REPUBLIC OF CHINA (PRC)****1. Planning Information****A. Effectivity**

PC-6 aircraft MSNs 974, 976, 985 thru 993, 995 thru 1002 and 1005 thru 1011.

B. Concurrent Requirements

None.

C. Reason**(1) Problem**

The S-TEC Autopilot STC is not yet validated by the CAAC.

(2) Solution

Install a placard to temporarily prohibit the use of the S-TEC Autopilot until CAAC validation is complete.

D. Description

This Service Bulletin gives the data and instructions to install a placard to temporarily prohibit the use of the S-TEC Autopilot.

NOTE: A Temporary Revision supplied with this Service Bulletin is to be inserted into Aircraft Flight Manual Supplement (AFMS) 02342 to provide the data for the placard.

E. Compliance

Required for aircraft registered in the PRC that have the S-TEC Autopilot installed.

Part A:

Part A of this Service Bulletin should be accomplished at the next opportunity.

Part B:

Part B of this Service Bulletin is to be accomplished on receipt of confirmation of CAAC validation of the S-TEC Autopilot STC.

F. Approval

The Technical content of this Service Bulletin is approved under the authority of DOA No. EASA. 21J. 357.

PILATUS advises Operators/Owners to check with their local Airworthiness Authorities for any changes, local regulations or sanctions that may affect the embodiment of this Service Bulletin.

G. Copyright

© Pilatus Aircraft Ltd. This document contains proprietary information that is protected by copyright. All rights are reserved. No part of this document may be copied, reproduced or translated to other languages without the prior written consent of Pilatus Aircraft Ltd.

H. Manpower

	Part A	Part B
Modification	0.75	0.5
TOTAL MAN-HOURS	0.75	0.5

I. Weight and Balance**(1) Weight Change**

None.

(2) Moment Change

None.

J. Electrical Load Data

Not changed.

K. Software

Not changed.

L. References

Aircraft Maintenance Manual (AMM): 20-31-00.

M. Publications Affected

AFMS 02342.

N. Interchangeability of Parts

Not affected.

2. Material Information**A. Material - Price and Availability**

No Modification Kit is required for this Service Bulletin.

Operators should send orders for parts to their Customer Liaison Manager at Pilatus Aircraft Ltd.,
6371 Stans, Switzerland.