

Service Bulletin No: 04-017

Ref No: 325

Modification No: EC-08-0167

ATA Chapter: 04

**AIRWORTHINESS LIMITATIONS - GENERAL
FEDERAL AVIATION OFFICE, GERMANY - CERTIFICATION STANDARD PC-12/47E AIRCRAFT****1. Planning Information****A. Effectivity**

PC-12/47E aircraft which are required to comply with the Federal Aviation Office, Germany (LBA) certification standard.

B. Concurrent Requirements

None.

C. Reason**(1) Problem**

To have the aircraft in compliance with the requirements of the LBA, Germany.

(2) Cause

The LBA require that placards for passengers shall be written in the German language.

(3) Solution

Install placards in accordance with the language requirements of the LBA.

D. Description

This Service Bulletin gives the instructions and data necessary to install the language placards.

Revision 1 to this Service Bulletin:

- Updates the effectivity of this Service Bulletin
- Adds a legal statement
- Updates the modification kit and adds sealant
- Updates Figure 1 to the latest revision.

Operators who have already accomplished this Service Bulletin at a previous issue do not need to do further work.

E. Compliance

Mandatory for all aircraft which are required to be in compliance with the LBA, Germany certification standard.

F. Approval

The technical content of this Service Bulletin is approved under the authority of DOA No. EASA.21J.357.

PILATUS advises Operators/Owners to check with their designated Airworthiness Authority for any changes, local regulations or sanctions that may affect the embodiment of this Service Bulletin.

G. Copyright and Legal Statement

© Pilatus Aircraft Ltd. This document contains proprietary information that is protected by copyright. All rights are reserved. No part of this document may be copied, reproduced or translated to other languages without the prior written consent of Pilatus Aircraft Ltd.

In connection with the use of this document, Pilatus does not provide any express or implied warranties and expressly disclaims any warranty of merchantability or fitness for a particular purpose. This document contains trade secrets, confidential and/or proprietary information of Pilatus and technical data subject to export control laws and regulations, including the U.S. Export Administration Regulations (EAR). Disclosure or distribution of this document contrary to the EAR, and other laws and regulations, is strictly forbidden. The above restrictions may apply to data on all pages of this document.

H. Manpower

Task	Man-hours
Preparation	0.50
Installation	1.00
Close Up	0.50
TOTAL MAN-HOURS	2.00

I. Weight and Balance

No change.

J. Electrical Load Data

No change.

K. Software

Pilatus ensures configuration control.

L. References

AMM: 12-B-20-31-00-00A-070A-A

M. Publications Affected

None.

N. Interchangeability of Parts

Not applicable.

2. Material Information**A. Material - Price and Availability**

Operators that require additional information and/or Service Bulletin Material should contact their authorized Pilatus Service Center, or Pilatus Customer Support on www.pilatus-aircraft.com → contact us

NOTE: Part Numbers given in this Service Bulletin are correct at the time of approval. Pilatus Aircraft Ltd. reserves the right to change part numbers as necessary. Part numbers of items delivered are correct when dispatched. This could lead to differences between those part numbers quoted in this Service Bulletin and if parts are superseded. Operators are requested to check the IPD for delivered parts which differ from those listed in the Service Bulletin Materials Kit List.