## TEMPORARY REVISION NO. 15 TO PC-12/47E PILOT'S OPERATING HANDBOOK

## **USE OF FMS DIRECT-TO-RECOVERY PROHIBITED**

This Temporary Revision is for aircraft MSN 545, 1001 – 1270 Pre SB 45-005 (Build 7) only.

Record the incorporation of this Temporary Revision on the Log of Temporary Revisions.

## **SECTION 2 – LIMITATIONS**

PRIMUS APEX - FLIGHT MANAGEMENT SYSTEM

The following limitation is added to the Primus Apex – FMS limitations on page 2-26.

The use of the Primus Apex – Flight Management System, Direct-To-Recovery function, is prohibited at any phase of flight.

For all PC-12/47E aircraft Post SB 45-005 (Build 7), the above is not required as Build 7 fixes this problem.

FMS Runway Change Report No: 02277 Issued: May 19, 2010 1 of 1 Section 2