



PILATUS AIRCRAFT LTD. CH-6371 STANS, SWITZERLAND

FOR PLANNING PURPOSES

SERVICE BULLETIN

SERVICE BULLETIN NO: 11-003

REF NO: 160

MODIFICATION NO: 951161

ATA CHAPTER: 11

PLACARDS AND MARKINGS - INTERIOR PLACARDS INCORRECT PLACARD IN THE FLIGHT COMPARTMENT

1. Planning Information

A. Effectivity

All PC-12 and PC-12/45 aircraft MSN 101, MSN 103 thru MSN 120, MSN 122 thru MSN 165, MSN 167 thru MSN 175, MSN 178 thru MSN 289, MSN 291 thru MSN 333, MSN 335 thru MSN 341, MSN 345 thru MSN 380, MSN 382 thru MSN 410, MSN 413 thru MSN 435, MSN 437, MSN 438, MSN 440, MSN 443 and MSN 448.

B. Reason

(1) Problem

It is possible that some aircraft have Operational Limitation placards P/N: 511.32.12.120 installed that do not show the IFR clearance, although all aircraft are IFR approved.

(2) Cause

An unknown number of placards P/N: 511.32.12.120 were manufactured without the abbreviation IFR.

(3) Solution

Replace incorrect placards.

C. Description

This Service Bulletin (SB) gives the data and instructions to examine the two installed placards and replace if incorrect.

D. Compliance

Mandatory.

Required not later than Dec 31, 2002.

E. Approval

The technical aspects of this Service Bulletin are approved by the Federal Office for Civil Aviation (FOCA) of Switzerland as an Airworthiness Directive.

PILATUS advises Operators/Owners to check with their local Airworthiness Authorities for any changes, local regulations or sanctions that can affect the embodiment of this Service Bulletin.

F. Manpower

	Total Inspection only	Total If Placard Replaced
Inspection	0.25	0.25
Replace Placard		0.25
TOTAL MAN-HOURS	0.25	0.50

NOTE: Man-hours figures do not include the time required to cure sealants and adhesives.

G. Weight and Balance

(1) Weight Change

Not affected.

(2) Moment Change

Not affected.

H. Electrical Load Data

Not changed.

I. Software

Not changed.

J. References

Illustrated Parts Catalog (IPC), 11-30-01.

K. Publications Affected

Not affected.

L. Interchangeability of Parts

Not applicable.

2. Material Information

A. Material - Price and Availability

Operators should send orders for placards, to their Authorized Pilatus Service Center, or to:

PILATUS AIRCRAFT LTD.,
CUSTOMER LIAISON MANAGER,
CH-6371 STANS,
SWITZERLAND

General Aviation:
Tel : + 41 41 619 6319
Fax: + 41 41 619 6224
eMail: pilga@pilatus-aircraft.com

Government:
Tel : + 41 41 619 6509
Fax. + 41 41 619 6224
eMail: rpaterson@pilatus-aircraft.com

PILATUS BUSINESS AIRCRAFT LTD.,
PRODUCT SUPPORT DEPARTMENT
11755 AIRPORT WAY
BROOMFIELD, CO 80021.
UNITED STATES OF AMERICA

Tel : 303 465 9099
Fax: 303 465 6040
eMail: Productsupport@PilBal.com

PILATUS AUSTRALIA (Pty.) LTD.,
PO BOX 732
MARLESTON SA 5033
AUSTRALIA

Tel : (08) 8234 4433
Fax: (08) 8234 4499
Free Call: 1800 445 007
eMail: info@pilatus.com.au

Operators are requested to advise Pilatus Aircraft Ltd, of the Manufacturer's Serial Number (MSN) and the flying hours of aircraft which are affected by this Service Bulletin.