

Service Bulletin No: 26-001

Ref No: 257

Modification No: EC-10-0188

ATA Chapter: 26

**FIRE PROTECTION - EXTINGUISHING
TO PROVIDE AN ALTERNATIVE COCKPIT FIRE EXTINGUISHER****1. Planning Information****A. Effectivity:**

All PC-12 series aircraft.

B. Concurrent Requirements

None.

C. Reason

To provide an alternative cockpit fire extinguisher.

D. Description

This Service Bulletin gives the data and instructions necessary to:

- Remove the installed fire extinguisher and mounting bracket
- Modify the new mounting bracket
- Install a new fire extinguisher, modified bracket and a new clamp.

E. Compliance

Optional.

F. Approval

The technical content of this Service Bulletin is approved under the authority of DOA No. EASA. 21J. 357.

PILATUS advises Operators/Owners to check with their local Airworthiness Authorities for any changes, local regulations or sanctions that may affect the embodiment of this Service Bulletin.

G. Manpower

	Total
Removal	0.25
Modify the new mounting bracket	0.5
Installation	0.25
TOTAL MAN-HOURS	1.0

H. Weight and Balance**(1) Weight Change**

+ 0,42 kg (+0.92 lb)

(2) Arm

4,506 m (177.4 in)

(3) Moment Change

1,893 kg-m (164.26 lb-in)

I. Electrical Load Data

Not changed.

J. Software

Not changed.

K. References

Aircraft Maintenance Manual (AMM): 12-A-20-31-00-00A-070A-A, 12-B-20-31-00-00A-070A-A.

Illustrated Parts Catalog (IPC): 12-A-26-20-00-010-941A-A, 12-A-26-20-01-01A-941A-A,
12-A-26-20-01-01C-941A-A, 12-B-26-20-01-010-941A-A.

L. Publications Affected

IPC, AMM.

M. Interchangeability of Parts

Interchangeable only as an assembly (fire extinguisher/bracket/strap as an assembly).

2. Material Information**A. Material - Price and Availability**

Pilatus advise that the standard lead times for the material needed in this Service Bulletin may be up to 6 weeks.

Operators should send orders for Service Bulletin Modification Kits, to their Authorized Pilatus Service Center. If additional information is needed, please contact:

PILATUS AIRCRAFT LTD.,
CUSTOMER SUPPORT MANAGER,
CH-6371 STANS,
SWITZERLAND

General Aviation:
Tel: + 41 41 619 3333
Fax: + 41 41 619 7311
eMail: SupportPC12@pilatus-aircraft.com

PILATUS BUSINESS AIRCRAFT LTD.,
PRODUCT SUPPORT DEPARTMENT
11755 AIRPORT WAY
BROOMFIELD, CO 80021.
UNITED STATES OF AMERICA

Tel: 303 465 9099
Fax: 303 465 6040
eMail: Productsupport@PilBal.com

PILATUS AUSTRALIA (PTY.) LTD,
17 JAMES SCHOFIELD DRIVE,
ADELAIDE AIRPORT SA 5950,
AUSTRALIA

Tel: (08) 8234 4433
Fax: (08) 8234 4499
Free Call: 1800 445 007
eMail: supportpc12@pilatus.com.au

Operators are requested to advise Pilatus Aircraft Ltd, of the Manufacturer's Serial Number (MSN) and the flying hours of aircraft which are affected by this Service Bulletin.