

Service Bulletin No: 72-005

Ref No: 329

Modification No:

ATA Chapter: 72

**ENGINE - INSPECTION OF FUEL NOZZLE TIPS - P&WC SERVICE BULLETIN NO. 14495****1. Planning Information****A. Effectivity**

All PC-12, PC-12/45, PC-12/47 aircraft from MSN 101 up to and including 888 and all PT6A-67B engines held as spare.

All PC-12/47E aircraft MSN 545 and MSN 1001 thru 1521 and all PT6A-67P engines up to serial number RY0550.

PT6A-67P engine serial numbers from RY0551 and up are not affected unless a fuel nozzle change has been incorporated.

**B. Concurrent Requirements**

None.

**C. Reason**

(1) Refer to P&WC Service Bulletin No. 14495, latest revision.

(2) Cause

Refer to P&WC Service Bulletin No. 14495, latest revision.

(3) Solution

Remove from service the fuel nozzle tips which have the date codes given in the P&WC Service Bulletin No. 14495, latest revision.

**D. Description**

Refer to P&WC Service Bulletin No. 14495, latest revision.

**E. Compliance**

Mandatory and in compliance with the P&WC Service Bulletin No. 14495, latest revision.

**F. Approval**

The technical content of this Service Bulletin is approved under the authority of DOA No. EASA. 21J. 357.

PILATUS advises Operators/Owners to check with their designated Airworthiness Authority for any changes, local regulations or sanctions that may affect the embodiment of this Service Bulletin.

**G. Copyright**

© Pilatus Aircraft Ltd. This document contains proprietary information that is protected by copyright. All rights are reserved. No part of this document may be copied, reproduced or translated to other languages without the prior written consent of Pilatus Aircraft Ltd.

**H. Manpower**

Refer to P&WC Service Bulletin No. 14495, latest revision.

**I. Weight and Balance**

No change.

**J. Electrical load Data**

No change.

**K. Software**

Not affected.

**L. References**

P&WC MM 3038336 Chapter 73-11-05.

P&WC Service Bulletin No. 14495, latest revision.

**M. Publications Affected**

None.

**N. Interchangeability of Parts**

N/A.

**2. Material Information****A. Material - Price and Availability**

Refer to P&WC Service Bulletin No. 14495, latest revision.

If you need more information about this Service Bulletin, please contact us as follows:

PILATUS AIRCRAFT LTD  
CUSTOMER SUPPORT MANAGER  
CH-6371 STANS  
SWITZERLAND

Tel: + 41 41 619 3333  
Fax: + 41 41 619 7311  
eMail: SupportPC12@pilatus-aircraft.com

PILATUS BUSINESS AIRCRAFT LTD  
PRODUCT SUPPORT DEPARTMENT  
11755 AIRPORT WAY  
BROOMFIELD, CO 80021  
UNITED STATES OF AMERICA

Tel: +1 303 465 9099  
Fax: +1 303 465 6040  
eMail: SupportPC12@PilBal.com

PILATUS AUSTRALIA (PTY.) LTD  
17 JAMES SCHOFIELD DRIVE  
ADELAIDE AIRPORT SA 5950  
AUSTRALIA

Tel: +61 8 8238 1600  
Fax: +61 8 8234 4499  
Free Call: +6 1800 PILATUS (745 2887)  
eMail: SupportPC-12@pilatus.com.au

Operators are requested to advise Pilatus Aircraft Ltd, of the Manufacturer's Serial Number (MSN) and the flying hours of aircraft which are affected by this Service Bulletin.

**B. Warranty**

P&WC Service Bulletin No. 14495, latest revision.

**C. Material Necessary for one Aircraft**

Refer to P&WC Service Bulletin No. 14495, latest revision.

**D. Operator Supplied Materials**

Not applicable.

**E. Tooling - Cost and Availability**

Not applicable.