



PILATUS AIRCRAFT LTD. CH-6371 STANS, SWITZERLAND

# SERVICE LETTER

**SUBJECT: CRANE LEAR ROMEC SERVICE BULLETIN RG9570-73-002 - FUEL PUMP - REPLACEMENT OF VALVE HOUSING AND RELATED SEALS**

To all Customers and Operators:

Date: Nov 15/00

This Service Letter is issued to draw attention to the following vendor information:

**Crane Lear Romec Service Bulletin RG9570-73-002 Dated Sep 22/00 - Engine Driven Fuel Pump, Pilatus Part No. 968.84.51.106 - Replacement of Valve Housing and Related Seals**

The SB gives the instructions on the modification of the Fuel Pump RG9570R1, which installs a new valve housing and seal.

Pilatus recommends the incorporation of this SB because it improves the sealing of the fuel pump relief valve.

If you have not received the Crane Lear Romec Service Bulletin direct from the Vendor, please contact them at the address given below:

Crane Lear Romec,  
Manager, Support Data,  
241 South Abbe Road,  
PO Box 1414,  
Elyria,  
Ohio 44036,  
USA

Tel: 440 2545493  
Fax: 440 3223378

Operators requiring further information on this subject, please contact one of the addresses given below:

PILATUS AIRCRAFT LTD.,  
CUSTOMER LIAISON MANAGER,  
CH-6371 STANS,  
SWITZERLAND.

or

PILATUS BUSINESS AIRCRAFT LTD.,  
PRODUCT SUPPORT DEPARTMENT,  
11755 AIRPORT WAY,  
BROOMFIELD, CO 80021.  
USA

Tel : + 41 41 619 6319 (General Aviation)  
Tel: + 41 41 619 6509 (Government)  
Fax: + 41 41 619 6224

Tel : 303 465 9099  
Fax: 303 465 6040

