



PILATUS AIRCRAFT LTD. CH-6371 STANS, SWITZERLAND

SERVICE LETTER

**SUBJECT: CRANE LEAR ROMEC SERVICE BULLETIN RG9570-73-002 - FUEL PUMP -
REPLACEMENT OF VALVE HOUSING AND RELATED SEALS**

To all Customers and Operators:

Date: May 17/01

This Service Letter is issued to draw attention to the following vendor information:

**Crane Lear Romec Service Bulletin RG9570-73-002 Dated Sep 22/00 - Engine Driven Fuel Pump,
Pilatus Part No. 968.84.51.106 - Replacement of Valve Housing and Related Seals**

The Vendor Service Bulletin gives instructions on the modification of the Fuel Pump RG9570R1, which installs a new valve housing and seal.

PILATUS recommends the incorporation of this SB because it improves the sealing of the fuel-pump relief valve.

Operators requiring further information on this subject, please contact one of the addresses given below:

PILATUS AIRCRAFT LTD.,
CUSTOMER LIAISON MANAGER,
CH-6371 STANS,
SWITZERLAND.

General Aviation
Tel : + 41 41 619 6319)
Fax: + 41 41 619 6224
eMail: pilga@pilatus-aircraft.com
Government
Tel: + 41 41 619 6509
Fax: + 41 41 619 6224
eMail: rpaterson@pilatus-aircraft.com

PILATUS BUSINESS AIRCRAFT LTD.,
PRODUCT SUPPORT DEPARTMENT,
11755 AIRPORT WAY,
BROOMFIELD, CO 80021.
USA

Tel : 303 465 9099
Fax: 303 465 6040
eMail: Productsupport@PilBal.com

PILATUS AUSTRALIA (Pty.) LTD.,
PO BOX 732,
MARLESTON SA 5033,
AUSTRALIA

Tel : (08) 8234 4433
Fax: (08) 8234 4499
Free Call: 1800 445 007
eMail: info@pilatus.com.au

