

SERVICE LETTER

SUBJECT: HONEYWELL AIR DATA COMPUTERS - MODIFICATION

To all Customers and Operators:

Date: May 17/05

This Service Letter is issued to draw attention to the following vendor information:

**Honeywell Service Bulletin: KDC 222-4
Air Data Computer for the KFC 325 Flight Control System**

Honeywell Service Bulletin KDC 222-4 introduces a modification to KDC 222 air data computers (ADCs) to help prevent nuisance autopilot disconnects in light to moderate air turbulence.

The nuisance disconnects can affect aircraft with KDC 222 units up to (and including) serial number 2459 with the following vendor part numbers: 065-0085-01, 065-0085-02, 065-0085-06, 065-0085-10 and 065-0085-20. KDC 222 units with serial number 2460 or greater are not affected.

Honeywell Service Bulletin KDC 222-4 gives instructions to incorporate a factory modification that consists of installing two filter capacitors in the G-dump circuit of the ADC.

PILATUS recommends Operators of aircraft with affected ADCs to have them modified in accordance with Honeywell Service Bulletin KDC 222-4.

Operators requiring further information on this subject, please contact one of the addresses given below:

PILATUS AIRCRAFT LTD.,
CUSTOMER SUPPORT MANAGER,
CH-6371 STANS,
SWITZERLAND.

General Aviation
Tel : + 41 41 619 6208
Fax: + 41 41 619 7311
eMail: SupportPC12@pilatus-aircraft.com
Government
Tel: + 41 41 619 6509
Fax: + 41 41 619 6224
eMail: rpaterson@pilatus-aircraft.com

PILATUS BUSINESS AIRCRAFT LTD.,
PRODUCT SUPPORT DEPARTMENT,
11755 AIRPORT WAY,
BROOMFIELD, CO 80021,
USA

Tel : 303 465 9099
Fax: 303 465 6040
eMail: Productsupport@PilBal.com

PILATUS AUSTRALIA (Pty.) LTD.,
PO BOX 732,
MARLESTON SA 5033,
AUSTRALIA

Tel : (08) 8234 4433
Fax: (08) 8234 4499
Free Call: 1800 445 007
eMail: info@pilatus.com.au

